lease print or type. (Form designed for use on elite (12-pitch) typewriter.)	The second secon		T 2 -			
UNIFORM HAZARDOUS "WASTE MANIFEST C A D O 8 6 5	PAID No. Ma Docui	inifest ment No.	2. Pag	is not law.	require	le shaded areas d by Federal
3. Generator's Name and Mailing Address Douglas Air 190th & Nort 4. Generator's Phone (200 66)27 Torrance, Ca	mandfe		84	e Manifest D 19243 e Generator's	96	t avumber
233-00//	US EPA ID Numi	har	C State	Transporte	% ID %	- 72-5
i i	D 0 5: 0:8 0 6	*		sporter's Ph		<u>408 / 5/ 6</u>
7. Transporter 2 Company Name 8.	US EPA ID Num		E.State		's 1813	585-5063
9. Designated Facility Name and Site Address 10.	US EPA ID Numi	ber	G.State	Facility's II)	
CASMALIA P.O. Box E NTU Road Casmalia, Ca 93429				lity's Phone	7.5	(<i>1/25</i>
IC A 11. US DOT Description (Including Proper Shipping Name, Hazard	0 0: 2:0:7:4 8 Class, and ID Number)	12.Conta		13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. Waste Sodium Hydroxide Liquid Corrocs*	ve UN1824	011	ПТ	04500	G	121
		7.77.		. * ! * * .	4	
b.						
C.	. 25%					
			.			
d.				en sentra en		
	*					
Sulfur 6% 4% 80% 86% 15. Special Handling Instructions and Additional Information Use gloves, goggles, respirator - May 6) ski		S.	
16. GENERATOR'S CERTIFICATION: I hereby declare that the conte above by proper shipping name and are classified, packed, mai for transport by highway according to applicable internation	rked, and labeled, and a	re in all re	spects i	n proper cond		Date
Printed/Typed Name	Signature	$H \rightarrow$	\mathcal{H}	/		Month Day Year
Donald C. Gerber sb	(Land 1/1	14	To 1			<u>0.81/3184</u>
17. Transporter 1 Acknowledgement of Receipt of Materials		-1	r	<u> 7 </u>		Date
Printed/Typed Name A A A A A A A A A A A A A A A A A A A	Signature	E.A.	de.	do		Month Day Year
Printed/Typed Name	Signature			<u>S</u>		Month Day Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardo	ous materials covered b	y this ma	nifest e	except as note	ed in	
Printed/Typed Name	Signature		1	1-1-	7	Date Month Day Year
Cara L. A.	1000 6	7			\mathscr{L}	181/c1/4
LUSARGIO PROSEURS	TO SESSION		11-71	- Marion	<i>~</i>	701 /1//

UNIFORM HAZARDOUS

WASTE MANIFEST

3. Generator's Name and Mailing Address

C4-700-86-0PC-0054

84924396

B.State Generator's ID

2. Page 1

of

Manifest

Document No.

Department of Health Services Toxic Substances Control Division Sacramento, California

Information in the shaded areas is not required by Federal

A.State Manifest Document Number

TANK 257 Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

1. Generator's US EPA ID No.

D 0 8 6 5 1 0 0 0

Douglas Aircraft Co. 190th & Normandie

5.	Generator's Phone (533-6677 Torrance, CA 90502 Transporter 1 Company Name 6. US EPA ID Nu	mber	C.State	Transporte	r's ID 7	08731
7.	Oil Process Co. Transporter 2 Company Name 8. US EPA ID Nu	C A D 0 5 0 8 0 6 8 5 0		sporter's Pho Transporter sporter's Pho	r's 1 01 3	585-5063
9.	Designated Facility Name and Site Address 10. US EPA ID Nu	mber	G.Stati	Facility's I)	
	CASMALIA P.O. Box E NTU Road Casmalia, Ca 93429	<u>n 1 4 5</u>	H.Faci	lity's Phone		
11.	US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Numbe	12.Con No.	tainers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a.	Waste Sodium Hydroxide Liquid Corrocsive UN1824	001.	TT	. 04500 .	6	121
b.			10000			
			1 1			
c.						
d.						
					1 1	
J.	Additional Descriptions for Materials Listed Above Sodium Hydroxide 8% 6% P.H. 12		K.Hani	dling Codes f	or Waste	es Listed Abov
J.			ZE	MPRO 508	33	es Listed Abovi
	Sodium Hydroxide 8% 6% P.H. 12 Sodium Aluminate 6% 4% Sulfur 6% 4% Mater 80% 86% Special Handling Instructions and Additional Information Guide #60 Use gloves, goggles, respirator - May cause severe GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consigning above by proper shipping name and are classified, packed, marked, and labeled, and labe	burns t	ZE to ski	MPRO 508 n and eye	33 as.	
	Sodium Hydroxide 8% 6% P.H. 12 Sodium Aluminate 6% 4% Sulfur 6% 4% Mater 80% 86% Special Handling Instructions and Additional Information Guide #60 Use gloves, goggles, respirator - May cause severe	burns t	ZE to ski	MPRO 508 n and eye	irlbed dition	Date
16	Sodium Hydroxide 8% 6% P.H. 12 Sodium Aluminate 6% 4% Sulfur 6% 4% Mater 80% 86% Special Handling Instructions and Additional Information Guide #60 Use gloves, goggles, respirator - May cause severe GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignm above by proper shipping name and are classified, packed, marked, and labeled, and for transport by highway according to applicable international and national government of the contents of the conte	burns t	ZE to ski	MPRO 508 n and eye	irlbed dition	Date
16	Sodium Hydroxide 8% 6% P.H. 12 Sodium Aluminate 6% 4% Sulfur 6% 4% Water 80% 86% Special Handling Instructions and Additional Information Guide #60 Use gloves, goggles, respirator - May cause severe GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignm above by proper shipping name and are classified, packed, marked, and labeled, and for transport by highway according to applicable international and national gov Printed/Typed Name Donald C. Gerber Transporter 1 Acknowledgement of Receipt of Materials	burns t	ZE to ski	MPRO 508 n and eye	33 25. Pribed dition	Date Month Day Ye
16	Sodium Hydroxide 8% 6% P.H. 12 Sodium Aluminate 6% 4% Sulfur 6% 4% Mater 80% 86% Special Handling Instructions and Additional Information Guide #50 Use gloves, goggles, respirator - May cause severe GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignm above by proper shipping name and are classified, packed, marked, and labeled, and for transport by highway according to applicable international and national gov Printed/Typed Name Donald C. Gerber Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Signature Signature Signature	burns t	ZE to ski	MPRO 508 n and eye	33 25. Pribed dition	Date Month Day Ye
16	Sodium Hydroxide 8% 6% P.H. 12 Sodium Aluminate 6% 4% Sulfur 6% 4% Water 80% 86% Special Handling Instructions and Additional Information Guide #60 Use gloves, goggles, respirator - May cause severe GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignm above by proper shipping name and are classified, packed, marked, and labeled, and for transport by highway according to applicable international and national gov Printed/Typed Name Donald C. Gerber Transporter 1 Acknowledgement of Receipt of Materials	burns t	ZE to ski	MPRO 508 n and eye	33 25. Pribed dition	

Signature

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

A

Date Month Day Year